PART III – Comments. Please reference comments on items responded to above in PART I or II, with Section letter and item number.
Note: Use additional pages if necessary.

Section B #16 Outlet in entry on Northside does not work. Center switch in switch plate in entry does not work. Plug ins for back porch and laundry do not work.

Section A #11 Sidewalk-sections replaced in 2013 due to new water lines from city installed.

Section D #7 - New sewer line installed Spring 2023

Section D-other -#15 Claims filed around 2019 -new roof installed

#16 Some cracks and holes

If checked here _____ PART III is continued on a separate page(s)